SI91.18-P-0002A Service Information: Discoloration, damage and creasing in seat covers

MODELS 129, 140, 163, 168, 169, 170, 171, 202, 203, 208, 209, 210, 211, 215, 220, 230, 414

Modification notes						
22.6.04	Contents	s have been completely updated				
 Due to recent events, we would like to draw your attention to the following information concerning customer complaints about fabric and leather upholstery. If, despite all efforts by the workshop, seat covers have to be replaced, these will continue to be inspected by the responsible warranty office. Prior to replacing seat covers, it must therefore be ensured that the damage was not caused by the customer through soiling of the upholstery or due to normal wear and tear. 			2.	2. Soiling of covers Possible cause: care/cleaning product Remedy: Regular care and cleaning of covers with Mercedes-Benz car care product (e.g. leather care foam A 001 986 59 71 10, fabric upholstery cleaner A 001 986 25 71)		
1. Discolo Possible Remedy	e cause:	overs colored clothing Clean covers with car care product (see Service Information: Polish and car care products for vehicle conditioning)	2.	Damage to covers Possible cause: Remedy:	Clothing, sharp objects Repair paint coat on leather covers (see AR - Repair paint coat of leather cover)	

Replacement of leather covers due to waves and creases which reflect natural leather formation is not warranty-relevant and **may be redebited** following warranty inspection.

Please remember that leather upholstery is a natural product that undergoes natural aging and that certain environmental influences (e.g. high humidity, high temperatures) may cause the leather to react in different ways (heavy creasing).

Service Information: Polish and car care products for vehicle conditioning	All models	SI98.30-P-0001A
Repair paint coat of leather cover	Model 129, 140, 163, 168, 170, 202, 203, 208, 209, 210, 211, 215, 220, 230, 414	AR98.00-P-0700A
Repair paint coat of leather cover	Model 169	AR98.00-P-0700AK
Repair paint coat of leather cover	Model 171	AR98.00-P-0700V