

MODEL 124, 126, 129, 140, 163, 168, 170, 201, 202, 208, 210

Revisions

8.9.98	Validities updated		
--------	--------------------	--	--

	Cause	Remedy	
	Various noise sources at contact points and surfaces on moving components in the seat adjustment mechanism cause noises under load and must be identified separately for each complaint.	<p>Note</p> <p>It is not always necessary to remove and disassemble the front seat in order to eliminate noises.</p> <p>Before removing the seat perform the following work to locate noises:</p> <ul style="list-style-type: none"> o Do not readjust seat o Try to reproduce noise while sitting on seat o Have second employee locate source of noise, e.g. backrest, seat cushion, seat adjustment, reclining seat fittings, coverings <p>When necessary remove seat and perform any remedies required only after identifying cause of noise according to this procedure.</p>	
		<p>It is not possible for cushion frames to cause noises which justify replacement of the cushion frame.</p> <p>For remedy measures see information in "Information up-date", group 91.</p>	