

**TRANSMISSION 722.6## ## as of 2871384 as of 17.4.01,
722.7## ## as of 0153700 as of 9.7.01**

To avoid malfunctions from metal particles, a magnet is placed in the oil pan.



The magnet can be retrofitted in the field.



P27.40-2027-01