

TRANSMISSION 722.6## /6## ## as of 1772285 as of 22.9.99

For reasons of cost, the oil drain plug on the torque converter has been deleted for all transmission variants.