

MODEL 163.136 /154 /172 #A as of 145273,
 163.136 /154 /172 #X as of 708319,
 163.113 /128 /174 /175

Damage Code	Cause	Remedy	
	Hood hinge lower support plate contacting upper sheet metal.	i In case of complaints: # 1 Locate noise.	
		2 Eliminate noise: #	
		Strengthen left hood hinge support Strengthen right hood hinge support	SM63.20-P-0002GH SM63.20-P-0003GI