

Company:
Address:
Telephone:

Report

2024-12-28 17:53

Vehicle Information

Vehicle Name : 211.056 - E 350 الاخير Year: 2009 VIN: WDBUF56X89B422891
Mileage : 518763km SN: A30M-106076
Diagnosis Route : Information -> System Selection -> Drive -> Motor electronics 9.7(ME 9.7)

Fault Codes

1 systems detected: 1 systems related to fault codes, 7 fault codes

NO.	System Name	Status
1	Motor electronics 7(ME 9.7)	▲ 7
0865	Voltage supply of component Motor electronics/Battery voltage too high(P0563)	Stored and Current
1345	B2/5 (Hot film mass air flow sensor):Loose contact with low frequency(P0104)	Stored and Current
0756	B6/5 (Right intake camshaft Hall sensor):The time of the signal value change is implausible.(P0341)	Stored and Current
0764	B6/7 (Right exhaust camshaft Hall sensor):The time of the signal value change is implausible.(P0366)	Stored and Current
0067	Component Y49/7 (Right camshaft exhaust solenoid) has an open circuit in the wiring.(P0013)	Stored and Current
0279	Component Y49/5 (Right camshaft intake solenoid) has an open circuit in the wiring.(P0010)	Stored and Current
0283	Component Y49/4 (Left camshaft intake solenoid) has an open circuit in the wiring.(P0020)	Stored and Current

Remark:

*This report is only responsible for the results of this detection: