


MODEL 163.113 /128 /136 /154 /157 /172 /174 /175 with CODE (580) Air conditioning or Tempmatic for USA

- 1 Cover
- 2 Bolt
- 3 A/C housing
- M2 Blower motor



P83.30-0764-06

☒ ☒	Remove/Install		
1	Remove cover (1) under the instrument panel (right)	i Up to VIN A145272, X708318. i As of VIN A145273, X708319.	AR68.10-P-1520GH AR68.10-P-1520GI
2	Unscrew bolt (2) from blower motor (M2)		
3	Disconnect connector from blower motor (M2)		
4	Remove blower motor (M2) from AC housing (3)		
5	Install in the reverse order		