

MODEL 163.136 /154 /172 #A as of 145273,
 163.136 /154 /172 #X as of 708319,
 163.113 /128 /157 /174 /175 with CODE (352a) COMAND operating and display system
 with video system

Operation no. of operation texts or standard texts and flat rates

Category	Op. no.	Operation text	Time	Acc. no.	Code
P	023898	Install interference suppression filter	014 WU	---	---

Damage code	Cause	Remedy	
	Signals from various control units may cause interference noise in the video system.	1 Install interference suppression filter.	SM82.60-P-0002GH